Montana AES: EARC-Sidney

Detail Map



Legend

- FUEL TANKS
- SEED BINS
- STRUCTURES
- PARCEL

Bld#	Name
8401	Superintendent Residence
8402	Cold storage
8403	Foreman residence
8404	Laboratory
8406	Granary/Grinding/Drying Lab
8409	Machine storage shed
8410	Machinery shed
8412	Foundation seed storage
8413	Huber seed cleaning/Processing/Packaging/Shop
8414	Seed bin (4)
8415	Main Office-Lab clsrms, Mtg rm, Labs, Grnhs
8416	Machine storage
8417	Machine storage shed
8418	Gas Tanks

0 100 200 400 Feet

1 inch = 200 feet

Copyright:© 2013 Esri, DeLorme, NAVTEQ, TomTom, Source: Esri, DigitalGlobe, GeoEye, i-cubed, USDA, USGS, AEX, Getmapping, Aerogrid, IGN, IGP, swisstopo, and the GIS User Community

Site Boundary Map 2

47.780751, -104.246608
+47° 46' 50.70", -104° 14' 47.79"



Source: Esri, DigitalGlobe, GeoEye, i-cubed, USDA, USGS, AEX, Getmapping, Aerogrid, IGN, IGP, swisstopo, and the GIS User Community

Vicinity Map



Sources: Esri, DeLorme, NAVTEQ, USGS, Intermap, iPC, NRCAN, Esri China (Thailand),

Site Boundary Map 1



47.727724, -104.148160
+47° 43' 39.81", -104° 8' 53.38"

Source: Esri, DigitalGlobe, GeoE
Getmapping, Aerogrid, IGN, IGP,

Date: 6/25/2013

Drawn by Christian Black
Source: Montana GIS Portal http://gisportal.msl.mt.gov
FacilitesInventory updated April 2013
Contact FPDC Analyst Matt Hume



MONTANA STATE UNIVERSITY

Montana State University
Facilities Planning, Design & Construction

This product is for informational purposes and may not have been prepared for, or be suitable for legal, engineering or surveying purposes. Users of this information should review or consult the primary data and information sources to ascertain the usability of the information.

Building Pictures of EARC

Photos originally taken 4/6/2011.
Pictures taken after 2011 are dated.
Pictures ordered by building number except where noted

Sections

1. Building Photos – Interior and Exterior Photos
2. Structures on Site that Are Not Buildings – Bins, Propane Tanks
3. Other Site Issues

Interior and Exterior Photos of Buildings

1. BUILDING PHOTOS

Bldg #8401 – Superintendent Residence

Bldg #8402 – Cold Storage (Old Chem Storage – likely to be demoed)

Bldg #8403 – Foreman Residence

Bldg #8406 – Granary / Grinding / Drying Lab

Bldg #8406 – Granary / Grinding / Drying Lab

Bldg #8406 – Granary / Grinding / Drying Lab

Bldg #8410 – Machinery Shed

Bldg #8410 – Machinery Shed

Bldg #8412 – Foundation Seed Storage

Bldg #8412 – Foundation Seed Storage

Bldg #8413 – Huber Seed Cleaning/Processing/Packaging/Shop

Shop part of Bldg #8413 (Heated)

Lab Part of Bldg #8413 - Seed Cleaning, Processing, and Packaging (Heated)

Storage part of Bldg #8413 (unheated)

Bldg #8415 – Main Offices with Lab Classrooms, Meeting Room, Labs, Greenhouse

Bldg #8415 – Main Offices with Lab Classrooms, Meeting Room, Labs, Greenhouse (East side)

Bldg #8415 – Main Offices with Lab Classrooms, Meeting Room, Labs, 2 Greenhouses (North side)

Bldg #8415 – Main Offices with Lab Classrooms, Meeting Room, Labs, 2 Greenhouses (East side)

Main Offices with Lab Classrooms, Meeting Room, Labs, 2 Greenhouses (East side)

Bldg #8415 - Meeting room w/ kitchen area and foldable divider down center to create two rooms

Bldg #8415 – Mechanical Spaces and Lab

Bldg #8415 – Main Offices with Lab Classrooms, Meeting Room, Labs, 2 Greenhouses (East side)

Bldg #8415 –Greenhouse (and adjacent support spaces to Greenhouse)

Bldg #8415 – Greenhouse Equipment

Bldg #8416 – Machine Storage



Bldg #8416 – Machine Storage

Bldg #8417 – Chemical Storage/Handling Facility

Bldg #8417 – Chemical Storage/Handling Facility

Photo updated 5/12/2015, new in 2014

New Building – Residence #3 (replaced bldg #8404)

Bins, Propane Tanks, Other

2. STRUCTURES ON SITE THAT ARE NOT BUILDINGS

Bldg #8418 - Fuel Tanks

Bldg #8414 – Seed Bins (4)

Bldg #8414 – Seed Bins; Bldg #8418 - Fuel Tanks

Fencing, drainage issues

3. OTHER SITE ISSUES

Photo taken 3/20/2014

Cracking Concrete (Poured 2013) around new building #8415.

Photo taken 3/20/2014

Cracking Concrete (Poured 2013) around new building #8415.

Photo taken 3/20/2014

Cracking Concrete (Poured 2013) around new building #8415.

Photo taken 3/20/2014

Cracking Concrete (Poured 2013) around new building #8415.

Cracking Concrete (Poured 2013) around new building #8415.

Cracking Concrete around new building #8415

Canals will eventually need some work

This pond is next to the new front office and is especially hard to see when it is snow covered. A car has been stuck in it.

Soft roads need gravel

More road issues –a trash truck picked up trash and left this tread into the soft ground as he left while Matt and George were visiting

Mud

Buildings that disappeared, etc

4. HISTORICAL PHOTOS

Bldg #8404 – Laboratory (Two Attached Greenhouses and their footprints are in the process of removal. They were recently sold. On)

Bldg #8404 – Laboratory (attached to Bldg #8411 – Two Greenhouses)